



Countries:	CANADA, UNITED STATES, PUERTO RICO	Document ID:	IK1600183
Availability:	ISIS, FleetISIS	Revision:	7
Major System:	CAB / SLEEPER / HOOD	Created:	5/9/2013
Current Language:	English	Last Modified:	2/4/2014
Other Languages:	NONE	Author:	
Viewed:	2296		

[Less Info](#)


Hide Details

Coding Information

Copy Link	Copy Relative Link	Bookmark	Add to Favorites	Print	Provide Feedback	Helpful	Not Helpful
		 View My Bookmarks				 18	 2

Title: Offensive Odors Inside Cabin

Applies To: Post 2010 ProStar

DESCRIPTION

Driver complaint of offensive odors in the cab.

TOOLS REQUIRED

General hand tools
1/4 inch drill bit
Drill

PARTS INFORMATION

Cowl Tray Kit : P/N 2511806C91

REPAIR PROCEDURE

Click on the following items:

[Diagnostic Flow Chart](#)

[Cowl Tray Installation Instructions.docx.pdf](#)

OTHER RESOURCES

Click on the following items:

[Exhaust Leak Troubleshooting for 2007](#)

-

[Exhaust Leak Troubleshooting for 2010 Emission](#)

[PDOG Clamp](#)

Click Here for: [Cowl Tray to Cab Seal Installation Procedure](#)

Click Here for: [Exhaust Manifold Ring Seal Removal / Installation](#)

Click Here for: [Exhaust Manifold Gasket Removal and Installation Procedure](#)

-

Warranty Information

NOTE:

- **File separate claim sections when addressing leaks at the cowl tray and the exhaust manifolds.**
-
- **If vehicle is beyond standard (01) warranty cowl tray repairs can be claimed under warranty code 40, under a separate claim section. This repair should NOT be done proactively (repair must address an "Odor in Cab" complaint). File claim using SRT A40-13665-1, and coding to group 13665 through Feb. 28, 2014.**

R16-1301A ProStar Cowl Tray, Replace 0.7 Hrs



Hide Details

Feedback Information

Viewed: 2295

Helpful: 18

Not Helpful: 2

No Feedback Found