



Countries:	AUSTRALIA, BRAZIL, CANADA, UNITED STATES, PUERTO RICO, SOUTH AFRICA	Document ID:	IK1300029
Availability:	ISIS	Revision:	3
Major System:	TRANSMISSION	Created:	8/24/2007
Current Language:	English	Last Modified:	4/28/2014
Other Languages:	Français , Español ,	Author:	Matthew Boyer
Viewed:	270		

[Less Info](#)

Hide Details

Coding Information

Copy Link	Copy Relative Link	Bookmark	Add to Favorites	Print	Provide Feedback	Helpful	Not Helpful
		 View My Bookmarks				 54	 62

Title: Roll Pins Backing Out of Bell Crank on HPV with Manual Transmission

Applies To: All HPV with Manual Transmission

DESCRIPTION

If you are having problems with the roll pins backing out of the bell crank, you need to replace the bell crank with the part # below. There is a new bell crank available that has thicker walls.

[Parts Information](#)

2593367C91 Updated Bell Crank Kit (comes with new roll pin)

Hide Details

Feedback Information

Viewed:	269
Helpful:	54
Not Helpful:	62
No Feedback Found	

Copyright © 2014 Navistar, Inc.