

Date	Expiration	Release	Page
04.2014	04.2016	0	1(3)

## ENGINE DOOR CYLINDER ANCHOR CHECK H SERIES Prevost vehicles

### DESCRIPTION

On the vehicles affected by this bulletin, tighten the ball studs on the engine bay door gas springs


### MODEL YEAR(S) AND VEHICLES INVOLVED

<b>NOTICE TO SERVICE CENTERS</b> <i>Verify vehicle eligibility by checking warranty bulletin status with <b>SAP</b> or via <b>ONLINE WARRANTY SYSTEM</b> available on Service / Warranty tab of Prevost website.</i>	
<b>Model</b>	<b>VIN</b>
H3-41, H3-45 coaches Model Year : 2012- 2014	From 2PCH33490 <u>CC712042</u> up to 2PCH33497 <u>EC712610</u> incl.
H3-45 VIP motorhomes Model Year : 2012 - 2014	From 2PCV33496 <u>CC712047</u> up to 2PCVS3491 <u>EC712608</u> incl.
<b>This bulletin does not necessarily apply to all the above-mentioned vehicles, some vehicles may have been modified before delivery. The owners of the vehicles affected by this bulletin will be advised by a letter indicating the Vehicle Identification Number (VIN) of each vehicle concerned.</b>	

### MATERIAL NEEDED

No parts are required for this bulletin.

### PROCEDURE

 <b>DANGER</b>
Park vehicle safely, apply parking brake, stop engine. In the battery box, set the battery cut-off switch to the OFF position prior to working on the vehicle.




Figure 1



Figure 2

- 1) Tighten the ball studs hand-tight at the indicated locations (3 places) (Fig 1, 2).
- 2) Tighten by the stud hex section. Do not try to tighten the nuts on the bracket as they are welded.
- 3) Test door operation.

Date	Expiration	Release	Page
04.2014	04.2016	0	3(3)

## PARTS / WASTE DISPOSAL

Discard waste according to applicable environmental regulations (Municipal/State[Prov.]/ Federal)

## ESTIMATED TIME

The time required to perform this special bulletin is approximately 15 minutes.

## OTHER

VBC Bulletin	N/A
Fail Code	18.05
Defect Code	09
System Condition	B
Causal Part	980015

Prevost engages in a continuous program of testing and evaluating to provide the best possible product. Prevost, however, is not committed to, or liable for updating existing products.