

Toyota Motor Sales, U.S.A., Inc. 19001 South Western Avenue Torrance, CA 90501 (310) 468-4000

To: All Toyota Dealer Principals,

Service Managers, Parts Managers

Subject: Warranty Enhancement Program – ZE1

2007-2011 Model Year Camry Hybrid Vehicles

Extension of Warranty Coverage for Brake Actuator Assembly and Skid Control ECU/Brake

Pedal Stroke Sensor

In our continuing efforts to ensure the best in customer satisfaction, Toyota is announcing a Warranty Enhancement Program to extend the warranty coverage for repairs related to internal malfunctions of the Brake Actuator assembly or inaccurate monitoring logic of the Brake Pedal Stroke Sensor on 2007-2011 MY Camry Hyrid Vehicles.

In these vehicles, Toyota has received some reports where various brake system related warning lamps illuminate due to internal malfunctions of the Brake Actuator assembly. Separately, the same warning lamps may also illuminate due to overly sensitive monitoring logic for the Brake Pedal Stroke Sensor.

Although the Brake Actuator assembly and Skid Control ECU are covered by Toyota's New Vehicle Limited Warranty for 3 years or 36,000 miles (whichever occurs first), we at Toyota care about the customers' ownership experience. Toyota is now extending the warranty coverage for repairs related to internal malfunctions of the Brake Actuator assembly or overly sensitive monitoring logic for the Brake Pedal Stroke Sensor. Please see the Warranty Enhancement Program Details for additional information.

The following information is provided to inform you and your staff of the program notification schedule and your degree of involvement.

1. Owner Notification Letter Mailing Date

The owner notification will commence in Early July, 2014 and will be mailed over several months. We have attached a sample owner letter for your reference.

2. Warranty Enhancement Program Details

This Warranty Enhancement Program provides a Primary and Secondary coverage extension to the vehicle's "New Vehicle Limited Warranty" for repairs related to internal malfunctions of the Brake Actuator assembly or overly sensitive monitoring logic for the Brake Pedal Stroke Sensor. If the condition is related to an internal malfunction of the Brake Actuator, it will be replaced with a new one at **no charge**. If the condition is caused by overly sensitive monitoring logic for the Brake Pedal Stroke Sensor, the Skid Control ECU will be reprogrammed or replaced at **no charge**.

- The *Primary Coverage* offers warranty enhancement until *November 30, 2015 with no mileage limitation*.
- After the Primary Coverage period ends, *the Secondary Coverage* is applicable for <u>10</u> <u>years from the date of first use or 150,000 miles</u>, whichever occurs first.

This coverage is for warranty work performed at an authorized Toyota dealer only. It is subject to the same terms and conditions set forth in the New Vehicle Limited Warranty Section of your Owner's Warranty Information booklet. For example, damage from abuse, an accident, theft and/or vandalism is not covered by the New Vehicle Limited Warranty or this warranty enhancement.

3. Number and Identification of covered Vehicles

There are approximately 177,500 Vehicles covered by this Warranty Enhancement Program.

Please refer to Warranty Policy Bulletin (Bulletin No. POL14-04) for identification of vehicles covered by this Warranty Extension.

4. Warranty Claim Processing Instructions

Please refer to the Warranty Policy Bulletin (Bulletin No. POL14-04) for warranty claim processing instructions. *All parts replaced for this repair are subject to warranty parts recovery.*

5. <u>Technical Instructions (Repair Procedures)</u>


- Technical Instructions for Malfunctions of the Brake Actuator Assembly can be found in T-SB-0041-14
- Technical Instruction for overly sensitive monitor logic for the Brake Pedal Stroke Sensor can be found in T-SB-0040-14

6. Parts Ordering

As this is an extension of the warranty, most customers will only request reimbursement from TMS for past replacements. Dealers should not increase their stock of Brake Actuator Assemblies or Skid Control ECUs. As always, if a customer experiences one of the conditions described, dealers should conduct appropriate diagnosis and order the applicable parts.

Refer to Warranty Policy Bulletin POL14-04 for detailed parts ordering information.

Dealers are requested to only order parts for vehicles experiencing this condition. **DO NOT ORDER FOR STOCK.** The parts have been placed on Dealer Ordering Solutions and will be systematically released daily. Please see the weekly manual allocation report for additional details.



7. Customer Reimbursement

Please refer to the attached owner letter for reimbursement consideration instructions.

Please review this entire package with your Service and Parts staff to familiarize them with the proper step-bystep procedures required to implement this Warranty Extension.

As part of our dedication to continuous improvement, changes have been incorporated in the production process to ensure the highest quality products are provided to our customers.

Thank you for your cooperation.

TOYOTA MOTOR SALES, U.S.A., INC.