



Service Bulletin

PRELIMINARY INFORMATION

Subject: Service Transmission Light Flashing And Code P0705 Setting

Models: 2014-2015 Cadillac CTS Sedan
Equipped with Aisin TL-80SN 8spd automatic transmission RPO (MGG)

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

Some customers may comment on a transmission concern where the SES light is illuminated or the service transmission light is flashing.

Customers may also comment that the shifter does not seem to shift correctly into each range

Technicians may find P0705 in the TCM as active or history codes.

Note: Technicians may find U codes set but it is not consistent on which ones set or which module they set in.

Recommendation/Instructions

Contact the General Motors technical assistance center for a possible resolution for the transmission concerns listed above.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION