

Service Bulletin

PRELIMINARY INFORMATION

Subject: Informational Front And Rear Fuse Block Terminated Leads

Models: 2011-2015 Chevrolet Volt

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

During normal diagnosis, a dealer technician may comment that they cannot locate the Terminals for the following fuse blocks to perform a service repair

- 1. X51L Left Instrument Fuse block
- 2. X51R Right Instrument Fuse block
- 3. X53 Rear Fuse block

Recommendation/Instructions

The Terminal is a rosebud terminated lead that is currently not available from SPO. At this time, the terminated leads can only be ordered through the Warranty Parts Center (WPC).

Parts Information

Model year	WPC Part Number	Description	Qty
2011-2013	WPC 707	Terminated Lead for Rear Fuse Box	1
2011-2013	WPC 708	Terminated Lead for Front Fuse Boxes	1

Complete the WPC parts request form found below. Please use the proper terminated lead that is required for your vehicle by requesting the proper WPC part number listed above

For complete form do not enlarge before printing

WPC Parts Request Form

Use this form ONLY for U.S. & Canada Dealers. Export markets & Mexico Dealers must contact their regional Technical Assistance Center for assistance.

To: Warranty Parts Center "E-Mail" warrantypartscenterusa@gm.com or WPC Fax #: 248-371-0192

Attn: Amina Winfrey

Part Being Requested:

(1)WPC #	Quantity
----------	----------

(2)WPC # Quantity _____

(3)WPC # Quantity _____

(4)WPC # Quantity ____

Dealer BAC (U.S.) / Dealer Code (Canada):

Dealer Name:

Dealer Address:

Dealer Contact Person:

Dealer Phone Number:

Repair Order Number:

Vehicle VIN:

If you do not receive the part within 2 business days after emailing or faxing your part request to the Warranty Parts Center, please call Customer Assistance at 248-371-9901/9902

Warranty Information

For wiring repairs covered under warranty, please refer to latest version of bulletin 10-00-89-005 for warranty information on wire/connector repairs.

ADDITIONAL SI KEYWORDS:

bec block fuse fuseblock lbec lead terminal terminated wire

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION