

Model series 246/176/117 center stowa- ge compartment closes/opens with difficulty

Topic number	LI68.20-P-058749
Version	2
Design group	68.20 Center console
Date	10-29-2014
Validity	Model series 246/176/117 up to production date 30.6.2013 only with automatic transmission (code 429)
Reason for change	B Class added
Reason for block	

Complaint:

The center stowage compartment does not open or close smoothly.

Cause:

The guide rail for the lid jams.

Remedy:

Replace operating lever/ guide rail:
 Remove stowage compartment (AR.6820-P-2420NKB)
 Remove operating lever/ guide rail at side (see picture).
 Install new operating lever/ guide rail (A176 766 00 00 or A246 766 00 00) in the reverse order.

Attachments	
File	Description
Ausbau Betätigungshebel - Führungsschiene A176 766 00 00.jpg	Work procedure for removal of operating lever/ guide rail (A176 766 00 00)

Symptoms
Body / Interior equipment / Interior trim / Bad fitting
Body / Interior equipment / Stowage box/tray / Warped/twisted/distorted

Parts						
Part number	ES1	ES2	Designation	Quantity	Note	EPC
A 176 766 00 00			Operating lever/ guide rail	1		X
A 246 766 00 00			Operating lever/ guide rail	1		X

WIS-References			
Document number	Title	Note	Allocation

AR68.20-p-2420NKB	Remove stowage compartment or ashtray housing		Remedy
-------------------	---	--	--------

Validity		
Vehicle	Engine	Transmission
*	*	724.003
*	*	724.001
*	*	724.011
*	*	724.020
*	*	724.002
*	*	724.004
*	*	724.015
*	*	724.206
*	*	724.208
117.301	*	*
117.303	*	*
117.312	*	*
117.342	*	*
117.343	*	*
117.344	*	*
117.346	*	*
117.352	*	*
176.000	*	*
176.001	*	*
176.002	*	*
176.003	*	*
176.005	*	*
176.007	*	*
176.008	*	*
176.011	*	*
176.012	*	*
176.042	*	*
176.043	*	*
176.044	*	*
176.046	*	*
176.052	*	*
242.848	*	*
242.890	*	*
246.200	*	*
246.201	*	*
246.202	*	*
246.203	*	*

246.205	*	*
246.207	*	*
246.208	*	*
246.211	*	*
246.212	*	*
246.242	*	*
246.243	*	*
246.244	*	*
246.246	*	*
246.247	*	*

Attachments

Ausbau Betätigungshebel - Führungsschiene
A176 766 00 00.jpg:

