

## Procedure in case of slight oil traces on TRANSMISSION 722.9 with CODE B03

Topic number	LI27.55-P-058976
Version	2
Design group	27.55 Transmission oil cooling
Date	05-07-2014
Validity	Vehicles with TRANSMISSION 722.9 and CODE B03 (Eco Start-Stop)
Reason for change	Version after complete translation
Reason for block	

### Complaint:

- Possible slight oil traces at the connections of the transmission fluid line or on the transmission oil pan.
- Possible slight oil traces at the joint between the torque converter housing and the transmission housing.
- Possible slight oil traces on the auxiliary oil pump.
- Possible slight oil traces inside the torque converter housing.

### Cause:

Various possible root causes.

### Remedy:

See diagnosis tree in attachment. When referring to TIPS case, please instead create PTSS case. These PTSS cases are for data collection purposes. Please do not wait to release the vehicle once repaired.

Attachments	
File	Designation
Fault tree Procedure with small oil marks at the NAG2_ NAG2i.pdf	Diagnosis tree

### Symptoms

Power transmission / Automatic transmission / Automatic transmission, leaks / Leaks

Validity		
Vehicle	Engine	Transmission
218.303	651	722
218.323	642	722
218.326	642	722
218.355	276.952	722.906
218.359	276.952	722.906

218.393	642	722
218.394	642	722
218.903	651	722
218.923	642	722
218.959	276.952	722.906
218.993	642	722
C (204)	642	722
C (204)	276	722
C (204)	651	722
C (204)	274	722
CL (216)	278	722
CLS (218)	278	722
E (207)	642	722
E (207)	276	722
E (207)	651	722
E (207)	278	722
E (207)	274	722
E (212)	642	722
E (212)	276	722
E (212)	651	722
E (212)	278	722
E (212)	274	722
G (463)	273	722
G (463)	642	722
GL (166)	276	722
GL (166)	278	722
GL (166)	642	722
GLK (204)	642	722
GLK (204)	276	722
GLK (204)	651	722
GLK (204)	274	722
M (166)	642	722
M (166)	276	722
M (166)	651	722
M (166)	278	722
S (222)	642	722
S (222)	276	722
S (222)	278	722
SL (231)	276	722
SL (231)	278	722
SLK (172)	276	722
SLK (172)	651	722

