

B-pillar trim in model series 117 chafed through

Topic number	LI68.30-P-059216
Version	1
Design group	68.30 Coverings, trim
Date	06-16-2014
Validity	Model series 117
Reason for change	
Reason for block	

Complaint:

The B-pillar trim in model series 117 is chafed through at the height of the belt outlet.

Attachments	
File	Description
CLA 001.jpg	Complaint
CLA 002.jpg	Complaint
CLA 004.jpg	Complaint
CLA 008.jpg	Complaint
CLA 009.jpg	Complaint

Cause:

The seat belt can chafe through the B-pillar trim.

Remedy:

Replacing the B-pillar trim does NOT remedy the problem at the present time.

A modification is planned for November/ December 2014.

The modified B-pillar trim will appear under a new part number and will be announced via Xentry/TIPS.

Symptoms
Body / Interior equipment / Interior trim / Deformed
Body / Interior equipment / Interior trim / Bad fitting
Body / Interior equipment / Interior trim / Pressure mark

Validity		
Vehicle	Engine	Transmission
CLA (117)	*	*

Attachments

CLA 001.jpg:



CLA 002.jpg:



CLA 004.jpg:



CLA 008.jpg:



CLA 009.jpg:

