

No double-clutching function (exhaust system sound) in transmission modes S and M

Topic number	LI54.21-P-059247
Version	1
Design group	54.21 Control modules/modules
Date	06-20-2014
Validity	212.x74/ x75/ x76/ x92 218.x74/ x76/ x92 463.272/ 273
Reason for change	
Reason for block	

Complaint:

No double-clutching function (exhaust system sound) in transmission modes S and M.

Cause:

Engine control unit software

Remedy:

Update Engine control unit software via XENTRY.

Note:

Use Xentry Diagnostics/ DAS version 03/2014 or higher

Symptoms
Power generation / Engine noise / Humming/droning
Power generation / Exhaust system / Exhaust System Noise / Droning
Power generation / Exhaust system / Exhaust System Noise / Humming
Power transmission / Power transmission, noise / Humming/droning

Work units				
Op. no.	Operation text	Time	Damage code	Note
			54575 90	

Validity		
Vehicle	Engine	Transmission
212.074	157.981	*

XENTRY

212.075	157.981	*
212.076	157.981	*
212.092	157.981	*
212.274	157.981	*
212.275	157.981	*
212.276	157.981	*
212.292	157.981	*
218.374	157.981	*
218.376	157.981	*
218.392	157.981	*
218.974	157.981	*
218.976	157.981	*
218.992	157.981	*
463.272	157.984	*
463.273	157.984	*