GPOP - Issue Review System

Part Number: 68003656A\$

Part Description: Header Latch

Issue If the rubber gasket is out of position it is not necessary to replace the part. Instead, **Description:** use a soft plastic tool and insert the tool's edge underneath the rubber gasket, and

lift up the edge and slide it backward onto the latch's metal bracket.

Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.