



**NUMBER:** 08-032-14

**GROUP:** Electrical

**DATE:** March 13, 2014

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of Chrysler Group LLC.*

**THIS SERVICE BULLETIN IS ALSO BEING RELEASED AS RAPID RESPONSE TRANSMITTAL (RRT) 14-027. ALL APPLICABLE SOLD AND UN-SOLD RRT VIN'S HAVE BEEN LOADED. TO VERIFY THAT THIS RRT SERVICE ACTION IS APPLICABLE TO THE VEHICLE, USE VIP OR PERFORM A VIN SEARCH IN TECHCONNECT. ALL REPAIRS ARE REIMBURSABLE WITHIN THE PROVISIONS OF WARRANTY.**

**SUBJECT:**

Missing: Vehicle System Interface Module Jumper

**OVERVIEW:**

This bulletin involves placing the missing wire harness jumper in the glove box for later installation.

**MODELS:**

2014	D2	3500 Pickup
2014	DD	3500 Cab Chassis
2014	DP	4500/5500 Cab Chassis

**NOTE: This bulletin applies to vehicles built on or after June 30, 2013 (MDH 0630XX) and on or before September 11, 2013 (MDH 0911XX). with Electronic Monitoring Module (Sales Codes XXS).**

**SYMPTOM/CONDITION:**

Vehicle System Interface Module (VSIM) jumper missing from glove box.

**DIAGNOSIS:**

If a customer's VIN is listed in VIP or your RRT VIN list, perform the repair. For all other customers that describe the symptom/condition, perform the Repair Procedure.

**PARTS REQUIRED:**

Qty.	Part No.	Description
1	68211680AA	WIRING, Jumper, Module

**REPAIR PROCEDURE:**

1. Place in the glove box for later installation, VSIM module wiring jumper.

**POLICY:**

Reimbursable within the provisions of the warranty.

**TIME ALLOWANCE:**

<b>Labor Operation No:</b>	<b>Description</b>	<b>Skill Category</b>	<b>Amount</b>
08-90-75-90	Wiring Harness, Body Wiring, VSIM Jumper (0 - Low Skilled)	6 - Electrical and Body Systems	0.0 Hrs.

	<b>Related</b>		
95-08-90-90	Place VSIM Jumper Wiring In Glove Box Handling Fee		\$5.00

**NOTE: Handling fee is only applicable during the active RRT coverage and paid in US dollars.**

**FAILURE CODE:**

ZZ	Service Action
----	----------------