

Service Bulletin

PRELIMINARY INFORMATION

- Subject: Missing Nut on Stud for 100 Amp Fuse
- Models: 2014 Chevrolet Corvette

Condition/Concern



The purpose of the PI is to inform the customer and dealership personnel that the stud for the 100 amp fuse does not require a nut as shown in the illustration above. This fuse block is a common part and the Corvette does not use the 100 amp fuse.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION