



NUMBER: 03-001-14 REV. A

GROUP: Differential &
Driveline

DATE: June 28, 2014

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of Chrysler Group LLC.

THIS SERVICE BULLETIN IS ALSO BEING RELEASED AS RAPID RESPONSE TRANSMITTAL (RRT) 14-049. ALL APPLICABLE UN-SOLD RRT VIN's HAVE BEEN LOADED. TO VERIFY THAT THIS RRT SERVICE ACTION IS APPLICABLE TO THE UN-SOLD VEHICLE, USE VIP OR PERFORM A VIN SEARCH IN TECHCONNECT. FOR VEHICLES NOT INCLUDED IN THE RRT VIN LIST, APPLICATION OF THIS SERVICE BULLETIN TO SOLD UNITS IS BASED UPON THE CUSTOMER EXPERIENCING THE SYMPTOM/CONDITIONS. ALL REPAIRS ARE REIMBURSABLE WITHIN THE PROVISIONS OF WARRANTY.

THIS BULLETIN SUPERSEDES SERVICE BULLETIN 03-001-14, DATED JUNE 27, 2014, WHICH SHOULD BE REMOVED FROM YOUR FILES. ALL REVISIONS ARE HIGHLIGHTED WITH **ASTERISKS**** AND INCLUDE ADDITIONAL REQUIRED PARTS.**

SUBJECT:

Front Half Shaft Boot Clamp Loose

OVERVIEW:

This bulletin involves replacing both front half shafts.

MODELS:

2014	WD	Durango
2014	WK	Grand Cherokee

NOTE: This bulletin applies to vehicles built between March 2, 2014 (MDH 0302XX) and April 21, 2014 (MDH 0421XX).

SYMPTOM/CONDITION:

Some vehicles may have been built with loose front half shaft boot clamps. A loose front half shaft boot clamp could allow the boot to come loose allowing moisture and debris into the CV joint.

DIAGNOSIS:

If a customer's VIN is listed in VIP or your RRT VIN list, perform the repair procedure.

PARTS REQUIRED:

Qty.	Part No.	Description
1	52124712AC	Half Shaft Assembly, Right Front
1	52124713AC	Half Shaft Assembly, Left Front
2	04809863AC	Washer, Front Half Shaft to Hub and Bearing Assembly

REPAIR PROCEDURE:

1. Replace both front half shafts. Refer to DealerCONNECT>Service >TechCONNECT>Service Info>03 - Differential and Driveline>Half Shaft, Front>REMOVAL/INSTALLATION for additional information.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
02-13-05-9A	Front Half Shaft - Replace Both Sides (2 - Skilled)	3 - Driveline	1.2 Hrs.

FAILURE CODE:

ZZ	Service Action
----	----------------