

NUMBER: 19-004-14 REV. A

GROUP: Steering

DATE: November 25, 2014

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of Chrysler Group LLC.

THIS BULLETIN SUPERSEDES SERVICE BULLETIN 19-004-14, DATED NOVEMBER 01, 2014, WHICH SHOULD BE REMOVED FROM YOUR FILES. ALL REVISIONS ARE HIGHLIGHTED WITH **ASTERISKS** AND INCLUDE THE REMOVAL OF RAPID RESPONSE TRANSMITTAL (RRT) 14-093 VIN LIST.

SUBJECT:

Excess Leather On The Steering Wheel

OVERVIEW:

This bulletin involves inspecting and if necessary replacing the steering wheel.

MODELS:

2014 (LX) Chrysler 300

NOTE: This bulletin applies to vehicles built on or after January 13, 2014 (MDH 0113XX) and vehicles built on or before January 22, 2014 (MDH 1022XX) equipped with Leather Wrapped Steering Wheel (Sales Codes SCV or SCK or SCW).

SYMPTOM/CONDITION:

Excess leather on the steering wheel.

DIAGNOSIS:

If the customer describes the symptom, perform the Repair Procedure.

PARTS REQUIRED:

Qty.	Part No.	Description
1 (AR)	1VT811X9AB	Wheel, Steering (with speed control, heated steering wheel, and Uconnect voice command w/bluetooth)
1 (AR)	1XU941X9AB	Wheel, Steering (with adaptive speed control, heated steering wheel, and Uconnect voice command w/bluetooth)
1 (AR)	1VT821L9AB	Wheel, Steering (with real wood light olive ash and speed control)

Qty.	Part No.	Description
1 (AR)	1XU951X9AA	Wheel, Steering (with adaptive speed control, heated steering wheel, and Uconnect voice command w/bluetooth)
1 (AR)	5MA461L9AA	Wheel, Steering (with mochachino, adaptive speed control, heated steering wheel, and Uconnect voice command w/bluetooth, Satin titanium varvatos badging)
1 (AR)	5MA461X9AA	Wheel, Steering (with Dark Mocha/Black, adaptive speed control, heated steering wheel, and Uconnect voice command w/bluetooth, Satin titanium varvatos badging)
1 (AR)	1VT84DX9AB	Wheel, Steering (with Black/Lt. Frost Beige, adaptive speed control, heated steering wheel, and Uconnect voice command w/bluetooth)

REPAIR PROCEDURE:

- 1. Inspect the steering, is there excess leather as shown in (Fig. 1).
 - a. Yes>>> Remove and replace the steering wheel, Refer to the detailed service procedures available in DealerCONNECT> TechCONNECT under: Service Info> 19
 Steering> Column> Wheel, Steering> Removal/Installation.
 - b. No>>> Return the vehicle to the customer.



Fig. 1 Steering Wheel

- 1 Excess Leather
- 2 Backside of Steering Wheel
- 3 Front of Steering Wheel

POLICY:

Reimbursable within the provisions of the warranty. Pre-authorization through the Vehicle Digital Imaging Program is NOT required for this repair.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
19-85-01-99	Wheel, Steering - Inspect Only (2 - Skilled)	4 - Chassis Systems	0.2 Hrs.
19-85-01-9A	Wheel, Steering - Inspect and Replace (2 - Skilled)	4 - Chassis Systems	0.4 Hrs.

FAILURE CODE:

ZZ	Service Action
----	----------------