



NUMBER: 07-004-14

GROUP: Cooling

DATE: December 17, 2014

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of Chrysler Group LLC.

THIS SERVICE BULLETIN IS ALSO BEING RELEASED AS RAPID RESPONSE TRANSMITTAL (RRT) 14-103. ALL APPLICABLE SOLD AND UN-SOLD RRT VIN'S HAVE BEEN LOADED. TO VERIFY THAT THIS RRT SERVICE ACTION IS APPLICABLE TO THE VEHICLE, USE VIP OR PERFORM A VIN SEARCH IN TECHCONNECT. ALL REPAIRS ARE REIMBURSABLE WITHIN THE PROVISIONS OF WARRANTY.

SUBJECT:

Coolant Bottle Recovery Hose Improperly Attached

OVERVIEW:

Check the tie strap for the coolant bottle recovery hose and replace if required.

MODELS:

2014 (MK) Jeep Compass/Patriot

NOTE: This bulletin applies to vehicles built on or after September 07, 2014 (MDH 0907XX) and on or before September 08, 2014 (MDH 0908XX).

SYMPTOM/CONDITION:

Coolant bottle recovery hose may not be properly attached.

DIAGNOSIS:

If a customer's VIN is listed in VIP or your RRT VIN list, perform the repair.

PARTS REQUIRED:

Qty.	Part No.	Description
1 (AR)	04641780	Tie Strap

REPAIR PROCEDURE:

1. Check if the tie strap that holds the hose for the recovery bottle is properly attached. The tie strap may be installed backwards with the rough side facing outward, see (Fig. 1).



Fig. 1 Location Of The Tie Strap

On a support bracket, right front.

-
2. Is the tie strap properly attached?
 - a. Yes >>> This bulletin has been completed, use LOP (07-30-45-92) to close the active RRT.
 - b. No >>> Replace the tie strap and properly attach the hose.
 3. This bulletin has been completed, return the vehicle back to the stock or the customer.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
07-30-45-92	Tie Strap, Inspect and/or Replace (0 - Introduction)	8 - Engine Performance	0.2Hrs.

FAILURE CODE:

ZZ	Service Action
----	----------------