



SUBJECT

Gear Selector (GWS) Cannot Be Moved Into Sport or Manual Mode

MODEL

F15

SITUATION

Intermittently the gear selector switch cannot be moved into the left sport or manual position.

It is still possible to shift the vehicle from Park to Reverse, Drive or Neutral.

CAUSE

Internal fault in the GWS

CORRECTION

Work through any appropriate test plans if faults are stored for the GWS. If no faults are stored, replace the GWS.

PARTS INFORMATION

Refer to EPC for the correct part number of the GWS (trim level and option codes may differ).

WARRANTY INFORMATION

Covered under the terms of the BMW New Vehicle/SAV Limited Warranty or the BMW Certified Pre-Owned Programs

Defect Code:	61 31 71 15 00	
Labor Operation:	Labor Allowance:	Description:
00 00 006	Refer to KSD	Performing "vehicle test" (with vehicle diagnosis system – checking faults)
61 21 528	Refer to KSD2	Connect an approved battery charger/power supply (indicated in KSD2 as "Charging battery")
61 31 843	Refer to KSD	Replacing gear selector lever
61 00 730	Refer to KSD2	Programming/encoding control unit(s)

Labor operation code 00 00 006 is a Main labor operation. If you are already using a Main labor

code for another repair; use the Plus code labor operation 00 00 556 instead.

If correctly functioning control module(s) fail to reprogram or initializations are required, the additional work must be claimed using separate labor operations found in KSD2 under the defect code listed above.

Other Repairs

If performing ISTA diagnostics and related test plans results in other eligible and covered work, claim this work with the applicable defect code and/or labor operations listed in KSD2.

[Copyright ©2014 BMW of North America, Inc.]