



SI B51 08 07
Body Equipment

January 2014
Technical Service

This Service Information bulletin supersedes SI B51 08 07 **dated January 2010.**

NEW designates changes to this revision

SUBJECT

Erroneous Trunk Lid Open Check Control Message

MODEL

NEW E90

NEW E91

NEW E92

SITUATION

The trunk open check control message may appear, even though the trunk lid or tailgate is fully closed and latched.

CAUSE

Incorrect adjustment of the trunk latch striker

PROCEDURE

- Do not replace the trunk latch.
- Adjust the bump stops and striker per Repair Instruction RA 51 24 004.

WARRANTY INFORMATION

Covered under the terms of the BMW New Vehicle/SAV Limited Warranty

Defect Code:	51 24 00 79 00	
Labor Operation:	Labor Allowance:	Description:
NEW 51 24 004	Refer to KSD2	Adjusting luggage compartment lid lock

NEW Labor operation code 51 24 004 is a Main labor operation. If you are using a Main labor code for another repair, use the Plus code labor operation 51 24 504 instead.

[Copyright ©2014 BMW of North America, Inc.]