



This Service Information bulletin supersedes SI B84 06 13 **dated May 2013**.

NEW designates changes to this revision

SUBJECT

iPhone Charging Status Constantly Switches On and Off

MODEL

NEW .

F01, F02 (7 Series Sedan)

F02H (ActiveHybrid 7)

F06 (6 Series Gran Coupe)

F07 (5 Series Gran Turismo)

F10 (5 Series Sedan)

F10H (ActiveHybrid 5)

F12 (6 Series Convertible)

F13 (6 Series Coupe)

F15 (X5)

F25 (X3)

F30 (3 Series Sedan)

F30H (ActiveHybrid 3)

F31 (3 Series Sports Wagon)

F32 (4 Series Coupe)

F34 (3 Series Gran Turismo)

With option 609 (Navigation System Professional, HU-H)

and

Without option 6VA (CIC assignment)

SITUATION

When using the USB cable to connect the iPhone to the USB audio interface, the iPhone charging status constantly switches between charging and not charging. This is noticeable by the alternating flash in the battery symbol on the iPhone display.

CAUSE

The quality of the USB cable can cause a voltage drop (usually caused by using aftermarket cables).

INFORMATION

Do not replace any other parts!

Advise the customer that he/she **must** use one of the following:

- The original Apple iPhone/iPOD USB cable that came with the device
- A BMW supplied iPhone/iPOD USB adapter cable

PARTS INFORMATION

Part Number	Description	Quantity
61 12 2 220 019	USB Adapter for Apple iPhone/iPOD (Reference only)	1
NEW 61 12 2 354 478	BMW USB Adapter (Lightning)	1

WARRANTY INFORMATION

Not applicable.

[Copyright ©2014 BMW of North America, Inc.]