

Measure no.

US 57452661-01

Subject

Difficulty retrofitting the Gear Shift Assistant Pro

Status date (mm/dd/yy)

3/12/14

Status

Accepted

Organization

US, MOT

Date created (mm/dd/yy)

3/12/14

Created by

Rainer Wanninger

PQM Problem reference**Release date (mm/dd/yy)****Approved by****Dealer release**

Allow automatic release

Vehicles affected**E series**

K50

Engine**Body****Production period (from/to)**

(mm/dd/yy)

Comment on production period**Feedback (all cases relating to
measure up to) (mm/dd/yy)**

/

Complaint

Difficulty retrofitting the Gear Shift Assistant Pro

Cause

Early production or incorrect integration level.

Measure

The Gear Shift Assistant Pro can only be retrofitted on 2014 model year R 1200 GS (K50) produced from August 2013 (starting VIN Z184816) onward with an integration level of K001-14-02-500 or above. Vehicles produced during that time that have older integration levels must be flash programmed to integration level K001-14-02-500 or above before the Gear Shift Assistant Pro can be retrofitted.

Complaint**Fault location**

Technical Support

Fault typenot (sufficiently) suitable for
service**Fault place**

Cause

#

Fault location**Fault type****Fault place**

1

13/61 DME engine control
unit

Repair Task	Special Clearance	Area
Program/encode	No	Powertrain

Fault code

Progman / DIS / ISTA / ISTA/P

System	State	Version
--------	-------	---------

© 2002-2014 BMW OF NORTH AMERICA, LLC. ALL RIGHTS RESERVED.