



SUBJECT
Damage to Radiator when Removing Fan Cowl
MODEL

F56 (MINI Hardtop)

SITUATION

There is coolant leaking from the radiator after performing repairs where the fan cowl was removed.

CAUSE


Protruding parts or hose clamps come into contact with the radiator during fan cowl removal (1).

CORRECTION


Check for protruding parts or hose clamps before removing the fan shroud (1) per Repair Instruction RA 17 11 035, "Removing and installing/replacing fan cowl with electric fan."

WARRANTY INFORMATION

Not applicable.

