

**SUBJECT****N20 and N26 Injector Replacement****MODEL**

E84 (X1)

E89 (Z4)

F10 (5 Series Sedan)

F30 (3 Series Sedan)

F31 (3 Series Sports Wagon)

F32 (4 Series Coupe)

F33 (4 Series Convertible)

F34 (3 Series Gran Turismo)

F25 (X3)


INFORMATION

When a defective high-pressure fuel injector is identified with an **index “02”** designation, as shown in the illustration below, **all 4 injectors** must be replaced at the same time.

This bulletin only applies to **index “02”** injectors.

Index “01” and index “03” or higher are not affected.

No immediate repair is required **unless** the BMW vehicle is currently experiencing this problem.

**WARRANTY INFORMATION**

If an N20 or N26 engine's fuel injector(s) require replacement due to defect materials or workmanship during the applicable limited warranty coverage period, as outlined above, perform the appropriate repair to correct the problem.

[Copyright ©2014 BMW of North America, Inc.]