



This Service Information bulletin supersedes SI B71 01 14 **dated April 2014.**

PERFORM THE PROCEDURE OUTLINED IN THIS SERVICE INFORMATION ON ALL AFFECTED VEHICLES BEFORE CUSTOMER DELIVERY OR THE NEXT TIME THEY ARE IN THE SHOP FOR MAINTENANCE OR REPAIRS.

BMW centers must ensure Recalls are completed after having been notified by BMW of North America, LLC (BMWNA) that a safety-related defect or noncompliance exists in any motor vehicle or item of replacement equipment in the center's possession at the time of notification. In BMW NA's case, this notification would typically be made by the issuance of a Recall notification in the form of a Service Information bulletin (SIB) or transmission of a Dealer Communication System (DCS) Recall message.

Under the National Traffic and Motor Vehicle Safety Act of 1966, as amended, if a Recall Campaign is announced by BMW NA, centers must ensure that all Recalls on new vehicles and new items of replacement equipment are completed BEFORE delivery to the consumer. This means that centers may not legally deliver new motor vehicles or new items of replacement equipment to consumers with an open Recall.

The Safety Act also prohibits centers from selling or leasing the motor vehicle or item of replacement equipment, unless and until the open Recall has been completed BEFORE delivery. This also pertains to vehicles in the Certified Pre-Owned program, and to items of replacement equipment.

Finally, BMW centers should not sell or use parts that have been recalled by BMW NA. Please follow the specific instructions provided by BMW NA on the return or disposition of the parts.

NEW designates changes to this revision

SUBJECT

NEW Voluntary Emissions Recall Campaign 13E-A04: Replace Emissions Label

MODEL

F15 (X5 xDrive 35d)

NEW SITUATION

Certain 2014 model year F15 vehicles produced from March 13, 2014 through April 12, 2014. These vehicles are equipped with an "emissions" label with incorrect information pertaining to the model year.

Affected vehicles in dealer inventory must not be retailed or delivered until this issue is corrected. Vehicles at VDCs will be repaired prior to dealer delivery.

NEW AFFECTED VEHICLES

This Emissions Recall Campaign involves F15 vehicles with the N57T engine according to VIN selection.

First check if a Recall Completion Label, SD 92-435 for this campaign is already attached to the underside of the hood on the right (passenger) rear close to the windshield.

If the label is present, the Campaign has already been performed and no further action is necessary.

Affected vehicles which require this Recall Campaign to be completed will show it as "Open" when checked either in the "Service Menu" of DCSnet (Dealer Communication System) or with the Key Reader.


NEW PROCEDURE

1. Open the engine compartment hood. The label is located on the driver's side on the underside of the hood, close to the cowl/windshield.
2. Remove the incorrect label.
3. Clean the underhood surface with a suitable cleaning solution.
4. Affix the correct model year 2014 emissions label.

NEW PARTS INFORMATION

Part Number	Description	Quantity
71 22 8 579 192	Diesel MY 14 US Emissions label	1

LABEL INSTRUCTIONS

	<p>After the vehicle has been checked and corrected, obtain a label (SD 92-435) and with the indelible marker provided, legibly print the Recall name, Recall number, and dealer code (5 digits) on the "Emissions Recall Campaign Completed Label" (see illustration).</p> <p>Note: Additional labels can be ordered online at BMW TIS.</p>
---	---

Vehicle Emission Recall - Proof of Correction				
License Number	Make	Year Model	Body Type	Vehicle Identification Number
Manufacturer		Recall Number		
The above described vehicle has been repaired, modified and/or equipped with new emission control devices to meet applicable California Emission Control Laws.				
Dealer's Name		Address, City, State and Zip		
Date	Dealership's Authorized Signature			
Return this certificate to DMV <u>only</u> when required - otherwise retain for your records.				SD92-084

S12 96 U31

For California centers only: It is required by the California Code of Regulations that an executed orange "Vehicle Emission Recall - Proof of Correction" certificate (SD92-084, see illustration) be provided to each customer (for vehicles registered in the state of California), once the Recall on his or her vehicle has been completed.

NEW WARRANTY INFORMATION

Reimbursement for this Recall will be via normal claim entry utilizing the following information:

Defect Code:	00 71 04 02 00
---------------------	-----------------------

Completion before vehicle delivery to the customer or the vehicle is already in the workshop

Labor Operation:	Labor Allowance:	Description:
00 62 607	3 FRU	Replace emissions label

Labor operation code 00 62 607 is Plus labor operation.

Completion after vehicle delivery to the customer

Labor Operation:	Labor Allowance:	Description:
00 62 107	5 FRU	Replace emissions label

Labor operation code 00 62 107 is a Main labor operation, and as applicable, all other labor operations codes must be Plus code labor operations.

ATTACHMENTS

View PDF attachment [B710114 VIN List](#).

[Copyright ©2014 BMW of North America, Inc.]