

Measure no.	Subject	
US 58371638-01	Two lashing straps under pillion seat discontinued	
Status date (mm/dd/yy)	Status	Organization
4/29/14	Accepted	US, MOT
Date created (mm/dd/yy)	Created by	PQM Problem reference
4/29/14	Christine Koehling	
Release date (mm/dd/yy)	Approved by	Dealer release
		Allow automatic release

Vehicles affected

E series	Engine	Body
K42 K46 K46/11		
Production period (from/to) (mm/dd/yy)	Comment on production period	Feedback (all cases relating to measure up to) (mm/dd/yy)
/		

Complaint

There are only two lashing straps riveted down under my pillion seat instead of four.

Cause

The part has changed. When viewed in the direction of travel the two front lashing straps have been discontinued (see accompanying pictures).

Measure

Do not replace any parts and additional straps are not to be secured to a seat that has been fitted with two straps.

To securely lash luggage to the pillion seat, the customer should use the rear straps with extensions to the pillion passenger footrests.

The left-hand lashing strap should be secured to the right-hand pillion passenger footrest and vice versa.

Complaint

Fault location	Fault type	Fault place
46/63 Seat holding bridge	Missing, missing part	

Cause

#	Fault location	Fault type	Fault place
1	52/53 Seat cushion	Current revision index	
	Repair Task	Special Clearance	Area
		No	Body and Trim

Fault code

Progman / DIS / ISTA / ISTA/P

System	State	Version
--------	-------	---------

© 2002-2014 BMW OF NORTH AMERICA, LLC. ALL RIGHTS RESERVED.



