

**SUBJECT**

**FC 80402E Stored After Replacement of Rear Electronics Module**

**MODEL**

F33 (4 Series Convertible)

**SITUATION**

After replacement of the Rear Electronics Module (REM), fault code “0x80482E – Incorrect HW variant” is stored and cannot be cleared.

This fault has no effect on the vehicle functions and is not noticed by the customer.

**CAUSE**

The replacement REM is always supplied as a “High variant.”

The fault is stored because the F33 does not have a rear window anti-trap circuit.

**PROCEDURE**

The fault memory entry can be ignored.

[ Copyright ©2014 BMW of North America, Inc. ]