



PERFORM THE PROCEDURE OUTLINED IN THIS SERVICE INFORMATION ON ALL AFFECTED VEHICLES BEFORE CUSTOMER DELIVERY OR THE NEXT TIME THEY ARE IN THE SHOP FOR MAINTENANCE OR REPAIRS.

SUBJECT

Service Action: Replace Emission Label

MODEL

F02 (7 Series 740Ld xDrive Sedan)

F10 (5 Series 535d and 535d xDrive)

F25 (X3 xDrive 28d)

F30 (3 Series 328d and 328d xDrive Sedans)

F31 (3 Series 328d xDrive Sports Wagon)

SITUATION

Certain 2015 model year vehicles with N47T and N57T diesel engines were produced with an “emissions” label which contains incorrect information pertaining to the 2015 model year.

Affected vehicles in dealer inventory must not be retailed or delivered until this issue is corrected. Vehicles at VDCs will be repaired prior to dealer delivery.

AFFECTED VEHICLES

This Service Action involves certain F02, F10, F25, F30 and F31 vehicles with the N47T and N57T engines produced from 7/3/2014 to 7/25/2014 according to VIN selection.

First check if a Service Action label with a code number **700** is already attached to the B-pillar.

If a code number **700** has been punched out, the Campaign has already been performed and no further action is necessary.

Vehicles which require this Service Action to be completed will show it as “Open” when checked either in the “Service Menu” of DCSnet (Dealer Communication System) or with the Key Reader.

PROCEDURE

1. Open the engine compartment hood. The label is located on the driver’s side on the underside of the hood.
2. Remove the incorrect label.
3. Clean the underhood surface with a suitable cleaning solution.
4. Affix the correct model year 2015 emissions label.

PARTS INFORMATION

Part Number	Description	Quantity
71 22 8 586 416	F02, F10 MY15 US Diesel emissions label	1

71 22 8 586 418	F25 MY15 US Diesel emissions label	1
71 22 8 586 415	F30, F31 MY15 US Diesel emissions label	1

LABEL INSTRUCTIONS

	<p>This Service Action has been assigned code number 700. After the vehicle has been checked and/or corrected, obtain a label (SD 92-439) and:</p>
	<p>A. Emboss your BMW center warranty number in the middle of the label (1);</p> <p>B. Punch out code number 700 (2), printed on the label; and</p> <p>C. Affix the label to the B-pillar as shown.</p>

If the vehicle already has a label from a previous Service Action/Recall Campaign, affix the new label next to the old one. Do not affix one label on top of another one because a number from an underlying label could appear in the punched-out hole of the new label.

WARRANTY INFORMATION

Covered under the terms of the BMW New Vehicle/SAV Limited Warranty, or any applicable BMW or Federal Emissions Warranty.

Defect Code:	00 71 07 02 00	
Labor Operation:	Labor Allowance:	Description:
00 62 731	3 FRU	Replace emissions label

Labor operation code 00 62 731 is Plus labor operation.

[Copyright ©2014 BMW of North America, Inc.]