

From: [Broadcast Messaging System](#)
To: [DL-BMS_Message_Monitors](#)
Subject: Delivery Stop - F16 Radio Interference Due to Taillight Malfunction
Date: Friday, November 21, 2014 12:06:16 PM

Publish Date: November 21, 2014
From: Technical Service
Expiration Date: December 05, 2014

DCSnet Message
Urgent



Subject: **Delivery Stop - F16 Radio Interference Due to Taillight Malfunction**

Message Recipients: Service Technicians, General Managers, Service Managers, Shop Foremen, Service and Parts Managers

Message Text:

A Delivery Stop has been issued on certain F16 vehicles produced from August 1, 2014 through October 30, 2014. These vehicles may be equipped with a faulty taillight which causes radio reception interference at certain frequencies.

Affected vehicles in dealer inventory must not be retailed or delivered until this issue is corrected. Vehicles at ports of entry will be repaired prior to dealer delivery.

SI B63 13 14 will be updated with instructions and warranty information when it becomes available. Please contact your field representatives if you have any questions.

Affected vehicles can be identified with a "Vehicle Comment" in the DCS Warranty Vehicle Inquiry or ISPA Light with the description: "Delivery Stop – F16 radio reception interference. See SI B63 13 14. Defect code: 0063340100"

Sincerely,

Merita Fitzgibbon

Technical Service

Attachments:
No Attachments No Attachments

Recipients: BMW SAV (Light Trucks), All Offerings, All Regions, All Areas, All Departments, All Personnel
BMW Passenger Cars, All Offerings, All Regions, All Areas, All Departments, All Personnel

