

From: [Broadcast Messaging System](#)
To: [DL-BMS Message Monitors](#)
Subject: BMW i8 SIB and Defect Code Don't Match
Date: Wednesday, November 05, 2014 4:38:54 PM

Publish Date: November 05, 2014
From: Technical Service
Expiration Date: November 19, 2014

DCSnet Message
Important



Subject: **BMW i8 SIB and Defect Code Don't Match**

Service Technicians, General Managers, Service Managers, Shop Foremen, Service and Parts Managers

Message Text:

BMW i8 Defect Code 0016890100 (check fuel tank) was flagged in DCS with the incorrect Service Information bulletin B16 13 14. The message in DCS has been updated to state that the bulletin is not ready for publishing at this time and this will show in the key reader tomorrow. Therefore, no parts or repairs should be performed at this time for this Campaign.

Defect code 0016850100 (Fuel tank pump) was updated and will be released referring to SI B16 13 14 tomorrow morning. The VIN list of affected vehicles is below:

WBY2Z2C5XEVX64092	WBY2Z2C58EVX64074	WBY2Z2C53EVX64080	WBY2Z2C52EVX64085
WBY2Z2C53EVX64063	WBY2Z2C51EVX64076	WBY2Z2C58EVX64088	WBY2Z2C57EVX64079
WBY2Z2C53EVX64077	WBY2Z2C54EVX64069	WBY2Z2C57EVX64065	WBY2Z2C56EVX64073
WBY2Z2C50EVX64070	WBY2Z2C55EVX64081	WBY2Z2C52EVX64068	WBY2Z2C57EVX64082
WBY2Z2C59EVX64066	WBY2Z2C50EVX64084	WBY2Z2C50EVX64067	WBY2Z2C55EVX64078
WBY2Z2C5XEVX64075	WBY2Z2C54EVX64072	WBY2Z2C54EVX64086	

I apologize for any inconvenience this may have caused.

Sincerely, Eugene Aton, Technical Service

Attachments:

No Attachments No Attachments

Recipients: BMW i, All Offerings, All Regions, All Areas, All Departments, All Personnel