

Measure no.	Subject	
US 54810671-02	Incorrect road-speed indicated	
Status date (mm/dd/yy)	Status	Organization
9/25/14	Accepted	US, MOT
Date created (mm/dd/yy)	Created by	PQM Problem reference
9/25/14	Martin Bumba	
Release date (mm/dd/yy)	Approved by	Dealer release
		Allow automatic release

Vehicles affected		
E series	Engine	Body
K50		
Production period (from/to)		Feedback (all cases relating to
(mm/dd/yy)	Comment on production period	measure up to) (mm/dd/yy)
/		

Complaint
After switching off the ignition, the Speedometer needle is not in the zero position.

Cause
Due to process variations, it's possible for the Speedometer needle to turn on its shaft.

Measure
For detailed information, see Service Information Bulletin 62 002 13 (028) Speedometer.

Complaint		
Fault location	Fault type	Fault place
Display, speed	Display incorrect / not plausible	

Cause			
#	Fault location	Fault type	Fault place
1	62/11 Instrument cluster		
Repair Task	Special Clearance	Area	
Replace	No	Electrics/Electronics	

Fault code

Progman / DIS / ISTA / ISTA/P

System

State

Version

© 2002-2013 BMW OF NORTH AMERICA, LLC. ALL RIGHTS RESERVED.