

Measure no.

US 55685466-02

Subject

The cruise-control system is not working in the Enduro/Pro mode

Status date (mm/dd/yy)

9/25/14

Status

Accepted

Organization

US, MOT

Date created (mm/dd/yy)

9/25/14

Created by

Martin Bumba

PQM Problem reference**Release date (mm/dd/yy)****Approved by****Dealer release**

Allow automatic release

Vehicles affected**E series**

K50

Engine**Body****Production period (from/to)**

(mm/dd/yy)

Comment on production period**Feedback (all cases relating to**

measure up to) (mm/dd/yy)

/

Complaint

The cruise-control system is not working (no longer working) in the Enduro and Enduro Pro modes.

Cause

Software change in the engine management system.

From model year 2014 (from production date August 19th 2013 onwards), the cruise-control system can no longer be activated in the Enduro and Enduro Pro modes.

Measure

If the engine control unit on vehicles from model year 2013 (production date up to August 18th 2013) has been programmed with ISTA/P version 50.2 or a more recent version, the cruise-control system can no longer be activated in the Enduro and Enduro Pro modes.

Inform the customer that after programming the engine control unit, this functional change occurs and will be retained in the future. This production status is intended to be retrofitted on all vehicles.

Complaint**Fault location****Fault type****Fault place**

Cruise control

Cannot be activated /
selected

Cause

#	Fault location	Fault type	Fault place
1	13/61 DME engine control unit		
Repair Task		Special Clearance	Area
No action		No	Electrics/Electronics

Fault code

Progman / DIS / ISTA / ISTA/P

System	State	Version
--------	-------	---------

© 2002-2013 BMW OF NORTH AMERICA, LLC. ALL RIGHTS RESERVED.