

Measure no.

US 55813536-02

Subject

Navigator V maintains a Bluetooth connection to a mobile phone for a short period

Status date (mm/dd/yy)

9/25/14

Status

Accepted

Organization

US, MOT

Date created (mm/dd/yy)

9/25/14

Created by

Martin Bumba

PQM Problem reference**Release date (mm/dd/yy)****Approved by****Dealer release**

Allow automatic release

Vehicles affected**Engine****Body****E`series**

K17 K18 K19 K21 K25

K25/02 K25/03 K25/11 K25/12 K25/31

K25/32 K25/HP K26 K26/02 K26/11

K27 K27/11 K28 K29 K29/HP K40 K40/11

K43

K43/11 K43/HV K44 K44/31 K47 K48 K50

K51 K52 K70/11 K71 K71/11 K72 K72/11

K73/02 K75

Feedback (all cases relating to**Production period (from/to)(mm/dd/yy) Comment on production period****measure up to) (mm/dd/yy)**

/

Complaint

The Bluetooth connection between Navigator V and the mobile phone only lasts for a few seconds.

Cause

Navigator V does not have an integrated loudspeaker and if there is no existing headset or communication system, the connection between the mobile phone and Navigator V is disconnected and information explaining this is displayed.

This only affects the telephone functions; the data connection to other mobile phone applications remains in place.

Measure

1. First, establish the connection to a communication system or headset
2. Connect the mobile phone.

Complaint

Fault location	Fault type	Fault place
77/52 Navigator	Communication fault	

Cause

#	Fault location	Fault type	Fault place
1	77/52 Navigator	Bogus fault / pseudo fault	
Repair Task	Special Clearance	Area	
No action	No	Electrics/Electronics	

Fault code

Progman / DIS / ISTA / ISTA/P

System	State	Version
---------------	--------------	----------------
