

**SUBJECT****Service Engine Soon (MIL) Lamp Illuminated with No Relevant Faults****MODEL**

I01 (i3 and i3 REx)

I12 (i8)

**INFORMATION**

If an i3 or i8 is brought in for service with a Service Engine Soon (MIL) lamp illuminated, or with a customer concern that the MIL is intermittently illuminated, troubleshoot with ISTA/D.

If these diagnostics do not lead to a root cause and a solution, do the following:

- Do not clear faults with ISTA/D.
- Use an aftermarket OBD scan tool to read out any P-codes that are present.
- Record any and all P-codes.
- Submit a TC PuMA case entitled Check Engine Light – No Relevant Faults to either “BMW i3 Powertrain Components” or “i8 Powertrain Components.”

The P-code and diagnosis summary should also be included.

**WARRANTY INFORMATION**

If performing other ISTA diagnostics and their related test plans and/or the PuMA case results with eligible and covered work, claim this work with the applicable defect code(s) and labor operations listed in KSD2.

[ Copyright ©2014 BMW of North America, Inc. ]