October 2014 Technical Service

SUBJECT

ISTA Premium Repair Instructions

MODEL

R55 (Cooper S Clubman)

R56 (Cooper S)

R57 (Cooper S Convertible)

INFORMATION

ISPI NEXT ISTA 3.45 introduces a new concept for displaying repair instructions. The new repair instructions have the following advantages compared to the old style:

- All instructions (preliminary and follow-up) needed for the repair are included; hyperlinks are no longer needed.
- All special tools needed for the repair can be viewed or printed from one tab in ISTA without leaving the repair instructions page.
- All technical data and torque specs for the repair can be viewed from one tab in ISTA without leaving the repair instructions page.

Currently repair instructions for the timing chain replacement "1131051 – Replace timing chain (N14)" have been converted to this new format.

Refer to the attachment which describes how to access and use the instructions.

To get initial feedback if any further changes are needed prior to converting all future repair instructions, we have converted the repair instructions used most often to this new concept.

Please use these repair instructions when applicable and provide feedback using the attached feedback form. The form can be sent directly to Paul Labrie at Paul.Labrie@bmwna.com.

Thanks for any feedback that you can provide.

Paul Labrie

Technical Service

201-571-5247

ATTACHMENTS

View PDF attachment M070114 Survey.

View PDF attachment M070114 Attachment.

[Copyright ©2014 BMW of North America, Inc.]