


**SUBJECT****Front Axle Brake Pad Wear Sensor Routing****MODEL**

F56 (Cooper Hardtop)

SITUATION

During brake service, the brake pad wear sensor cable may be incorrectly routed and also fastened to the front brake caliper's bleed valve dust cap. Incorrect routing of the brake sensor cable may cause damage to the cable or brake sensor, resulting in a brake warning message being displayed.

CORRECTION

During maintenance brake service, route the brake pad wear sensor cable correctly (as indicated on the illustration). Do not fasten it to the bleed valve dust cap!!!

WARRANTY INFORMATION

Not applicable.