

Measure no.	Subject	
US 24084855-02	DWA does not respond to the remote control	
Status date (mm/dd/yy)	Status	PQM Problem reference
9/25/14	Accepted	
Date created (mm/dd/yy)	Created by	Organization
9/25/14	Martin Bumba	US, MOT
Release date (mm/dd/yy)	Approved by	Dealer release
		Allow automatic release

Vehicles affected

E series

K25 K25/02 K25/11 K25/12 K26
K26/02 K27 K28 K29 K29/HP
K40 K40/11 K43 K43/11 K43/HV
K44 K44/31 K71 K72 K73/02

Engine

2-ZYL 4-ZYL

Body

Production period (from/to)

(mm/dd/yy)
/

Comment on production period

Feedback (all cases relating to measure up to) (mm/dd/yy)

Complaint

DWA is armed using the remote control after turning off the ignition. After 1 hour, the DWA no longer responds to the remote control. Within the first hour, the DWA can still be operated by remote control.

Cause

In order to minimise the discharge suffered by the motorcycle vehicle battery, the radio response of the DWA to the remote control is deactivated 1 hour after switching off the ignition. This prolongs the period during which the motorcycle is immobilised and after which an engine start is still possible.
The DWA function is retained.

Measure

A DWA which has been armed is automatically deactivated after turning on the ignition.

Complaint

Fault location	Fault type	Fault place	Fault conditions
DWA deactivate	Switch-off not possible		Remote key

Cause

#	Fault location	Fault type	Fault place
1	01/40 OWNER'S HANDBOOK / ON-BOARD LITERATURE	Labelling wrong / faulty	
Repair Task	Special Clearance	Area	
No action	No	Electrics/Electronics	

Fault code

Defect

Main group

65 radio and special equipment

Subgroup

75 Alarm system

Location

04 Receiver for alarm system

Defect code

6575041200

Defect description

Receiver for alarm system
failed

Module

86

Area Fault code

Electrics/Electronics

CIP / DIS

System

State

Version

Tech. Office report

Report no.

24162914

Subject

DWA does not respond to the
remote control

Link Condition

Approved

Measure AG

Measure no.

AG 24084855-01

Subject

DWA does not respond to the remote
control

© 2002-2009 BMW OF NORTH AMERICA, LLC. ALL RIGHTS RESERVED.