

Measure no.

US 50075232-02

Subject

Camber/inclination angle (Drop) sensor

Status date (mm/dd/yy)

10/1/14

Status

Accepted

Organization

US, MOT

Date created (mm/dd/yy)

10/1/14

Created by

Martin Bumba

PQM Problem reference**Release date (mm/dd/yy)****Approved by****Dealer release**

Allow automatic release

Vehicles affected**E series**

K46/11

Engine

4-ZYL

Body**Production period (from/to)**

(mm/dd/yy)

Comment on production period**Feedback (all cases relating to**

measure up to) (mm/dd/yy)

/

Complaint

The camber (drop) sensor (61 31 7 723 812) is not fitted in the usual wiring harness location.

Cause

On vehicles with the option code x129 (Race ABS + DTC), the drop sensor is integrated in the camber/inclination angle sensor box – leaving the usual drop sensor location vacant.

Therefore the drop sensor does not have to be retrofitted to vehicles with option x129.

On vehicles WITHOUT option x129 (race ABS + DTC), the drop sensor is fitted ex-factory in the usual wiring harness location.

Measure

Vehicles with the option x129 (race ABS + DTC) do not require a separate drop sensor to be fitted.

On vehicles WITHOUT option x129 (race ABS + DTC), the drop sensor should be fitted in the usual wiring harness location.

Complaint

	Fault location	Fault type	Fault place
▶	61/31 Drop sensor	Missing, missing part	

Cause

#	Fault location	Fault type	Fault place
▶ 1	61/31 Drop sensor	Missing, missing part	
	Repair Task	Special Clearance	Area
	No action	No	Electrics/Electronics

Fault code

Progman / DIS / ISTA / ISTA/P

System	State	Version
---------------	--------------	----------------
