



TECHNICAL SERVICE BULLETIN

DATE: July 28, 2014

SERVICE BULLETIN #463

TO: REGIONAL OPERATIONS AND SALES MANAGERS, DEALER
PRINCIPALS, PARTS AND SERVICE MANAGERS

FROM: BARRY A. MITCHELL
DIRECTOR, CUSTOMER SERVICE

SUBJECT: Meritor WABCO ABS ECU Corrosion Investigation

Recently we have experienced a number of reports regarding MeritorWABCO ABS ECU failures due to corrosion of the Sensor, Power and/or Dummy Plug connections.

Great Dane and MeritorWABCO are actively researching these concerns to determine the root cause and contributing factors. If you are contacted by MeritorWABCO for information related to any field issues that your location or customers have experienced we would ask your assistance in providing comprehensive information for our evaluation.

In the interim we would ask that prior to contacting Ontrac (866) 668-7221 regarding an ABS ECU concern where you suspect corrosion, that your service department obtains photos illustrating the following areas:

- ECU/Valve with all cables connected prior to unplugging any connector or cutting any cable ties. Multiple pictures preferred (Left, center and right side angles if possible)
- Corroded connectors, both on the ECU as well as on the mating cable
- Sensor cable routing to the ECU module

This will help to expedite the claim being presented. Thank you in advance for your assistance in our investigation.

If after your review of this information you should have any questions please feel free to contact Customer Service at (877) 369-3493.