

Implausible coolant warning message in instrument cluster

Topic number	LI20.00-P-057734
Version	2
Design group	20.00 General
Date	02-14-2014
Validity	176.052 117.352
Reason for change	Remedy updated
Reason for block	

Complaint:

Coolant warning message in the instrument cluster although the coolant level is OK

Note:

The warning message appears primarily during cornering maneuvers

Cause:

The warning threshold in Rear Signal Acquisition Module (SAM) is too sensitive

Remedy:

1. Check coolant level, correct if necessary
2. Perform SCN coding on rear SAM

Symptoms
Power generation / Engine cooling system / Cooling system indicator lamp / Illuminates yellow
Power generation / Engine cooling system / Cooling system display / Coolant - Serviced Required

Work units				
Op. no.	Operation text	Time	Damage code	Note
			5452E F1	

Validity		
Vehicle	Engine	Transmission
117.352	*	*
176.052	*	*