

## Creaking noises in area of center console for model series 117

Topic number	LI68.20-P-058781
Version	1
Design group	68.20 Center console
Date	03-31-2014
Validity	Model series 117 up to production date 24.02.2014
Reason for change	Modified validity for US market Added parts disclaimer
Reason for block	

**Complaint:**

Creaking noises in area of center console.

**Cause:**

The trim on the A/C operating unit makes noises.

Attachments	
File	Designation
1.JPG	EPC picture

**Remedy:**

Replacement of trim on A/C operating unit.

Determine the optimized trim parts via the EPC.

**Note:** Some parts may be non-stocking parts for MBUSA, and possibly C66 and not immediately available from DAG. Please be aware and check availability prior to scheduling customer repairs.

Symptoms
Body / Interior equipment / Instrument panel / Noise
Body / Interior equipment / Interior trim / Noise

Work units				
Op. no.	Operation text	Time	Damage code	Note
			68102 36	

WIS-References			
Document number	Title	Note	Allocation
ar68.20-p-2350nkb	Remove/install cover on center console		Remedy

Validity		
Vehicle	Engine	Transmission
117.301	*	*
117.303	*	*
117.312	*	*
117.342	*	*
117.343	*	*
117.344	*	*
117.345	*	*
117.346	*	*
117.352	*	*

Full model designation breakdown		
Vehicle	Engine	Transmission
117.301	651.901	711.642
117.301	651.901	724.003
117.303	651.930	724.003
117.312	607.951	711.632
117.312	607.951	724.020
117.342	270.910	711.632
117.342	270.910	711.643
117.342	270.910	724.002
117.343	270.910	711.643
117.343	270.910	724.002
117.344	270.920	724.003
117.345	270.920	724.003
117.346	270.920	724.011
117.352	133.980	724.015

Attachments

1.JPG:

