

## Rear door quarter window roller blind cover loose

Topic number	LI72.12-P-058637
Version	1
Design group	72.12 Rear door
Date	03-04-2014
Validity	Model series 222 with code 297, up to VIN end no.: 029143
Reason for change	
Reason for block	

### Complaint:

Rear door quarter window roller blind fails to extend.

### Cause:

Due to incorrect installation, the cap (Figure 1) can come loose.

This can cause the mechanism of the rear side roller blind in the quarter window to jump out of the guide (Figure 2).

Attachments	
File	Designation
Bild 1.JPG	Figure 1
Bild 2.JPG	Figure 2

### Remedy:

1. Position roller blind mechanism in guide (Figure 3).
2. Attach cap.

Note: In this case it is not necessary to replace the rear roller blind.

Attachments	
File	Designation
Bild 3.JPG	Figure 3

Symptoms
Body / Interior equipment / Sun protection / Roller sun blind, side window / Does not move in/out
Body / Interior equipment / Sun protection / Roller sun blind, side window / Comes unhooked

Work units				
Op. no.	Operation text	Time	Damage code	Note

			81A0E 38	
			81N0E 38	

Validity			
Vehicle	Engine	Transmission	
S (222)	*	*	

Full model designation breakdown			
Vehicle	Engine	Transmission	
222.004	651.921	724.208	
222.032	642.861	722.903	
222.032	642.861	725.011	
222.033	642.867	722.966	
222.057	276.960	724.206	
222.057	276.960	725.011	
222.077	157.985	722.931	
222.082	278.929	722.909	
222.082	278.929	725.011	
222.085	278.929	722.967	
222.085	278.929	725.041	
222.104	651.921	724.208	
222.123	642.861	722.903	
222.123	642.861	725.011	
222.132	642.861	722.903	
222.132	642.861	725.011	
222.133	642.867	722.966	
222.157	276.960	724.206	
222.157	276.960	725.011	
222.162	276.824	722.904	
222.162	276.824	725.011	
222.165	276.824	722.904	
222.165	276.824	725.011	
222.176	277.980	722.932	
222.177	157.985	722.931	
222.178	157.985	722.971	
222.179	279.980	722.932	
222.182	278.929	722.909	
222.182	278.929	725.011	
222.185	278.929	722.967	
222.185	278.929	725.041	