

Staining on Dinamica seat covers

Topic number	LI91.18-P-058808
Version	1
Design group	91.18 Seat covers
Date	03-28-2014
Validity	Model series W/S/X 204, W/S 212
Reason for change	
Reason for block	

Complaint:

White stains occur on the Dinamica covers in the areas of the cushion cover and backrest cover. (Pic.1- Pic.3)

Attachments	
File	Designation
Dinamica1.JPG	Staining on rear backrest
Dinamica2.JPG	Staining on seat cushion
Dinamica4.JPG	Staining on seat cushion

Cause:

Under analysis.

Remedy:

You will be notified via TIPS as soon as an appropriate remedy is available.

Until then, do not replace any covers with this issue.

Symptoms
Body / Seat / Seat cover / Staining

Parts							
Part number	ES1	ES2	Designation	Quantity	Note	EPC	Other make part
A 204 910 99 46			DRIVER CUSHION COVER / AVANTGARDE ARTICO DINAMICA			X	
A 204 910 94 05			HEATED DRIVER CUSHION COVER / AVANTGARDE ARTICO DINAMICA			X	
A 204 910 10 11			HEATED M DRIVER CUSHION COVER			X	

A 204 910 08 11			HEATED M DRIVER CUSHION COVER			X	
A 212 910 49 05			LEFT DRIVER CUSHION COVER			X	
A 204 910 95 05			LEFT DRIVER BACKREST COVER / SPORT ARTICO DINAMICA LUMBAR			X	
A 204 910 97 05			LEFT HEATED DRIVER BACKREST COVER / SPORT ARTICO DINAMICA LUMBAR			X	
A 204 910 01 06			LEFT DRIVER BACKREST COVER / SPORT ARTICO DINAMICA 4WL			X	
A 204 910 03 06			LEFT HEATED DRIVER BACKREST COVER / SPORT ARTICO DINAMICA 4WL			X	
A 212 910 55 05			LEFT MULTICONTOUR DRIVER CUSHION COVER			X	
A 212 920 39 02			REAR CUSHION COVER			X	
A 212 920 32 02			REAR CUSHION COVER			X	
A 212 920 91 02			REAR CUSHION COVER			X	
A 212 920 99 02			REAR CUSHION COVER			X	
A 204 920 25 02			LEFT REAR CUSHION COVER			X	
A 204 920 26 02			RIGHT REAR CUSHION COVER			X	
A 204 920 64 01			REAR CUSHION COVER			X	
A 204 920 08 61			REAR CUSHION COVER / AVANTGARDE ARTICO DINAMICA			X	
A 212 920 16 60			REAR BACKREST COVER / ARTICO SPORT LEATHER			X	
A 204 920 86 02			REAR BACKREST COVER			X	
A 204 920 65 01			LEFT REAR BACKREST COVER			X	
A 204 920 13 60			LEFT REAR BACKREST COVER / AVANTGARDE ARTICO DINAMICA			X	
A 204 920 29 02			LEFT REAR BACKREST COVER			X	
A 204 920 66 01			RIGHT REAR BACKREST COVER			X	
A 204 920 10 60			RIGHT REAR BACKREST COVER / AVANTGARDE ARTICO DINAMICA			X	
A 204 920 35 02			RIGHT REAR BACKREST COVER			X	
A 204 910 65 09			HEATED DRIVER CUSHION COVER			X	

A 204 910 66 09		DRIVER CUSHION COVER		X
A 204 910 62 09		HEATED DRIVER CUSHION COVER		X
A 204 910 62 10		DRIVER CUSHION COVER		X
A 212 910 50 05		RIGHT DRIVER CUSHION COVER		X
A 212 910 78 06		RIGHT DRIVER BACKREST COVER		X
A 212 910 85 05		LEFT DRIVER BACKREST COVER		X
A 204 910 99 47		LEFT DRIVER BACKREST COVER / TWIN DINAMICA		X
A 204 910 83 06		LEFT HEATED DRIVER BACKREST COVER / TWIN DINAMICA		X

Work units				
Op. no.	Operation text	Time	Damage code	Note
			91A04 26	Left front seat cushion cover
			91N04 26	Right front seat cushion cover
			91A15 26	Left front seat backrest cover
			91N15 26	Right front seat backrest cover
			92004 26	Rear seat cushion cover
			92013 26	Rear seat backrest cover
			92A73 26	Left rear seat backrest cover
			92N73 26	Right rear seat backrest cover
			92N63 26	Right rear seat cushion cover
			92A63 26	Left rear seat cushion cover

Validity		
Vehicle	Engine	Transmission
C (204)	*	*
E (212)	*	*
GLK (204)	*	*

Attachments

Dinamica1.JPG:



Dinamica2.JPG:



Dinamica4.JPG:

