

SERVICE CAMPAIGN BULLETIN

CAMPAIGN REF: 02I
TITLE : McLaren 650S – Oil Filler Cap Replacement
DOCUMENT # : 11 F 018
AFFECTED VEHICLES : McLaren 650S Coupe and Spider

SITUATION : Quality Engineering at McLaren Automotive have identified that a number of McLaren 650S have been fitted with oil filler caps that have the alignment marks missing.

PROCEDURE : Please follow the procedure outlined in this document.

INSTALLATION

1. Open Engine cover.
2. Replace existing oil filler cap with a new one.

Care Point: Ensure oil filler cap is refitted correctly, with the markings on the cap and bowl aligned. If not, it may become detached and allow oil to escape the system. If closed correctly the handle should be facing directly to the front of the car with the recesses parallel to the engine compartment side covers. Examples of correct (1) and incorrect installation (2) below.





Please contact your Regional Aftersales Manager should you have any questions relating to the information contained within this bulletin.

WARRANTY INFORMATION

DESCRIPTION	RESOLUTION CODE	TOTAL REPAIR TIME
Oil filler cap replacement	E0F20118A24O2K01	0.10 hours

PARTS INFORMATION

PART DESCRIPTION	PART NUMBER	QUANTITY	ORDER PROCESS
Oil Filler Cap	11F1596CP	1	Unipart