



Innovation
that excites

NISSAN BULLETIN

2011-13 Juke Timing Chain Voluntary Service Campaign ***Campaign Update 2***

Reference: P4213
Date: May 20, 2014

Attention: Dealer Principal, Sales, Service & Parts Managers

Parts Information:

Due to the damage of the Slack Guide Bolt (13094-EN200) during the removal procedure and the unforeseen part demand for the campaign, the slack guide bolt has been on backorder the last two weeks. Nissan will use part 13094-31U00 (Slack Guide Bolt-Alternative) as a temporary alternative to fill all VOR and CSC part backorders, which will arrive by Friday, 5/23 via FedEx. Nissan will be filling STK orders with the original part (13094-EN200) when further part supply is available next week. By June 2, Nissan will be in the position to supply natural demand using the original part (13094-EN200). For this reason the alternative part (13094-31U00) will not be chained to the original part (13094-EN200) and **dealers should not order the alternative part.**

Note: Dealers that receive the alternative part (13094-31U00) should submit that part (not the original part #) in the warranty claim.

Part Number	Description
13094-EN200 (Original Part)	Slack Guide Bolt
13094-31U00 (Alternate Part)	

Reminder: Dealers should not order alternative part (13094-31U00) as the part is only being used as a temporary measure to fill VOR and CSC backorders.

Bulletin Update:

Nissan has released an amended campaign technical service bulletin (NTB14-030a). Information regarding the timing chain tensioner and slack guide bolt were added on pages 22 and 23, and changes were made in the Parts Information. Please discard previous versions of this bulletin.