

Classification:

EM14-002a

Reference:

ITB14-031a

COPYRIGHT© NISSAN NORTH AMERICA, INC.

Date:

August 7, 2014

**2014 QX60 HYBRID;
WHINE/WHIRRING NOISE FROM SUPERCHARGER AT IDLE**

APPLIED VEHICLE: 2014 QX60 Hybrid (L50)**APPLIED ENGINE:** QR25DER

This bulletin has been cancelled. Please discard all previous copies of this bulletin and refer to the Electronic Service Manual for the procedure to replace the supercharger.