



SERVICE BULLETIN

Classification: EL14-048	Reference: NTB14-093	Date: September 23, 2014
-----------------------------	-------------------------	-----------------------------

2014-2015 XTERRA; LOW WINDSHIELD WASHER FLUID WARNING LAMP

APPLIED VEHICLES: 2014-2015 Xterra (N50)

SERVICE INFORMATION

The Applied Vehicles are not equipped with a Windshield Washer Fluid Level Sensor.

Therefore, a Low Windshield Washer Fluid Warning Lamp will not illuminate when the windshield washer tank is empty.



Not equipped

NOTE: The Windshield Washer Fluid Level Sensor is listed as “if so equipped” in the Electronic Service Manual (ESM) because it is installed in Canadian-market vehicles.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.