



# SERVICE BULLETIN

Classification:

RS14-016

Reference:

NTB14-111

Date:

December 2, 2014

## 2013 – 2015 SENTRA AND ALTIMA OCS SENSOR SERVICE PARTS

**APPLIED VEHICLES:** 2013 – 2015 Sentra (B17)  
2013 – 2015 Altima Sedan (L33)

### SERVICE INFORMATION

The OCS (Occupant Classification System) sensors for the Applied Vehicles are now available as service parts.

Amendments to the Electronic Service Manuals (ESMs) have been created and can be viewed at the following links:

Click [HERE](#) to view the 2013-2014 Sentra ESM amendment. (Procedure is included in the 2015 Sentra ESM.)

Click [HERE](#) to view the 2013 – 2015 Altima ESM amendment.

### PARTS INFORMATION

DESCRIPTION	MODEL	PART #	QUANTITY
Sen-Occupant (OCS Sensor)	Sentra and Altima	98853-3JA0A	Up to 2 per vehicle
M10 Nut (14 mm wrench size)	Sentra	23391-3NF0A	2
	Altima	23391-3JA0A	4
M8 Nut (12 mm wrench size)	Sentra	23188-3NF0A	2 for each sensor (up to 4)
	Altima	23188-3JA0A	

### CLAIMS INFORMATION

- The op-code for replacement of an OCS sensor is **RQ52AA**.
- Refer the Nissan Warranty Flat Rate Manual for any additional coding required for repairs that are performed.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.