

Measure no.

US 57066518-01

Subject

Front brake master cylinder cover leaking

Status date (mm/dd/yy)

1/24/14

Status

Accepted

Organization

US, MOT

Date created (mm/dd/yy)

1/24/14

Created by

Werner Uhrmann

PQM Problem reference**Release date (mm/dd/yy)****Approved by****Dealer release**

Allow automatic release

Vehicles affected**E series**

K50

Engine**Body****Production period (from/to)**

(mm/dd/yy)

Comment on production period**Feedback (all cases relating to**

measure up to) (mm/dd/yy)

/

Complaint

Brake fluid reservoir leaking

Cause

Front brake fluid expansion tank

Measure

For further analysis by the supplier, we require unopened handbrake fittings.

In the event of a verified complaint, do not attempt a repair. Create a PuMA case, replace the complete handbrake fitting and ship the unopened complete part to:

BMW AG

UX-VA-3, Werner Uhrmann

Hufelandstr. 20

80939 Munch

Germany

Complaint**Fault location****Fault type****Fault place**

34/31 Brake fluid expansion

Leak: Brake fluid

tank

Cause

#	Fault location	Fault type	Fault place
1	34/31 Brake fluid expansion tank	Leak: Brake fluid	
Repair Task	Special Clearance	Area	
	No	Chassis and Suspension	

Fault code

Progman / DIS / ISTA / ISTA/P

System	State	Version
--------	-------	---------