TECHNICAL BULLETIN LTB00590NAS2 28 APR 2014



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

This reissue replaces all previous versions. Please destroy all previous versions. Only refer to the electronic version of this Technical Bulletin in TOPIx.

Changes are highlighted in gray

SECTION: 412-01

Climate Control System Odor

AFFECTED VEHICLE RANGE:

Range Rover Sport (LW)

Model Year: 2014

VIN: EA300000-EA321100

Range Rover (LG)

Model Year: 2013-2014

VIN: DA001204-EA140400

<u> MARKETS:</u>

CAN, USA

CONDITION SUMMARY:

Situation: An odor may be present when the Climate Control System is switched 'ON'.

Cause: This may be caused by mold spore accumulation / build-up in the front evaporator core.

Action: Should a customer this express concern, follow the Service Instruction below.

PARTS:

LR056368 Evaporator Quantity: 1
LR055993 Particle Filter Quantity: 1

TOOLS:

No Tools Required

WARRANTY:

NOTE: Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to TOPIx to obtain the latest repair time.

NOTE: DDW requires the use of causal part numbers. Labor only claims must show the causal part

number with a quantity of zero.

| lumber with a quantity of zero. | | | | | |
|---|----------|-----------------|-------------------|----------------|--|
| DESCRIPTION | SRO | TIME (HOURS) | CONDITION CODE | CAUSAL PART | |
| Evaporator core - Renew - Range Rover Sport (L494) | 82.25.20 | 6.6 | 42 | LRO36365 | |
| Filter - Fresh air intake - Renew - Range Rover Sport (L494) | 80.15.42 | 0.1 | 42 | LRO36365 | |
| - | | | | | |

| Evaporator core - Renew - Range Rover (L405) | 82.25.20 | 7.1 | 42 | LRO36365 |
|---|----------|-----|----|----------|
| Filter - Fresh air intake - Renew - Range Rover (L405) | 80.15.42 | 0.1 | 42 | LRO36365 |

NOTE: Normal Warranty policies and procedures apply.

SERVICE INSTRUCTION:

1. NOTE: Prior to installation, wash out the evaporator core housing with warm water to remove any mold spore accumulation.

Replace the front evaporator (see TOPIx Workshop Manual, Section 412-01).

2. Replace the particle filter (see TOPIx Workshop Manual, Section 412-01).