

TECHNICAL BULLETIN
LTB00616NAS1
04 FEB 2014



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

SECTION: 417-01

Tail Lamp Condensation

AFFECTED VEHICLE RANGE:

Range Rover Evoque (LV)

Model Year: 2012 Onwards

VIN: CH000447 Onwards

MARKETS:

NAS

CONDITION SUMMARY:

Situation: The tail lamps may have condensation on the inner surface of the lens.

Cause: This may be due to there being no anti-mist coating on the inner surface of the tail lamp lens.



NOTE: Only the tail lamp with condensation may be replaced.

Action: Should a customer express this concern, follow the Service Instruction outlined below.

PARTS:

LR057981	Tail lamp - LH	Quantity: 1
LR057980	Tail lamp - RH	Quantity: 1

TOOLS:

Refer to Workshop Manual for any required special tools.

WARRANTY:



NOTE: Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to TOPIx to obtain the latest repair time.



NOTE: DDW requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Lamp assembly - Tail - Single - Renew	86.40.70	0.1	D8	LR037710
Lamp assembly - Tail - Pair - Renew	86.40.76	0.2	D8	LR037710



NOTE: Normal Warranty policies and procedures apply.

SERVICE INSTRUCTION:

1.  **NOTE: Only the tail lamp with condensation may be replaced.**

Install a new tail rear lamp assembly (refer to TOPIX Workshop Manual, Section 417-01).

- Repeat to other side only if necessary.