SSM66837
LR2 / L359
Gearshift Interlock Button / Spring Issue
Driveline
31-Oct-2014 00:00:00
503000 Automatic Transmission Engagement Concerns
Appendix 1 Gear Selector.pdf Appendix 2 Gear Selector.pdf
Issue: The gearshift interlock button inoperative or spring has come adrift (See Appendix 1)
Cause: The interlock button mechanism has been modified to prevent this issue from Vin No. H372254 UK Build L910950 Pune Build
Action: To copylyo this issue places replace the goar collector knob ONLY

To resolve this issue please replace the gear selector knob ONLY (See Appendix 2) $\,$

 $\label{eq:NOTE:power} \textbf{NOTE:} \ \ \textbf{Replacement of the complete assemby is NOT necessary}.$

Please only submit further EPQR's for any vehicles that are $\underline{\text{POST}}$ the above assured VIN's



